

# Contents

1	Introduction	6
2	Scope	7
3	Overview	8
3.1	NDT/NDE Methods	8
3.2	Imperfections and Defects	8
3.3	Destructive Testing	9
3.4	Acceptance Criteria	9
3.5	Inspection and Test Plan	9
4	Visual Inspection of Welds	11
4.1	Introduction	11
4.2	Welding Inspection Personnel	11
4.3	Conditions for Visual Inspection	11
4.4	Visual Inspection Duties	11
5	Weld Defects and Causes	15
5.1	Weld Technique	15
5.2	Weld Geometry, Shape and Dimensions	15
5.3	Cavities	17
5.4	Cracks	18
5.5	Solid Inclusions	20
5.6	Lack of Fusion or Penetration	21
6	NSSS Weld Acceptance Criteria	23